


Fuse Amp Color Code Identification Chart

Fuse Amp Rating		Color
1		Black
2		Gray
3		Violet
4		Pink
5		Tan
7.5		Brown
10		Red
15		Blue
20		Yellow
25		Clear
30		Green
35		Turquoise
40		Orange